


DIAMOND® EHT PINS FOR LEGUME HARVESTER APPLICATION

CHALLENGE -



A leading vegetable harvesting company was experiencing premature chain wear on its legume picking machine. In order to harvest these vegetables, roller chain comes in direct contact with dirt, which in turn causes an excess buildup of debris in the pin/bushing joint. This excess dirt eventually caused the competitor's chain to fail by wearing down the components.

SOLUTION -



RESULTS THAT MATTER -

After switching to Diamond® chain with EHT pins, wear life increased from 10 weeks to 16 weeks. This increase saved the harvesting company \$3,640 after one year and is projected to save \$18,200 after five years.



