


DIAMOND® O-RING CHAIN FOR AIR JACK APPLICATION

CHALLENGE -



A leading agriculture commodity processing company was experiencing constant downtime on each of its 30+ air jacks. Each air jack utilizes approximately 5 feet of chain and is not able to receive maintenance frequently. Due to the inability to perform regular maintenance, each air jack was failing after two weeks of use when using the competitor's chain.

SOLUTION -



RESULTS THAT MATTER -



After replacing the competitor's product with Diamond® o-ring chain, wear life increased from 2 weeks to 52 weeks. This increase saved the manufacturer \$6,500 after one year and is projected to save \$32,400 after five years.





